

NOTICE OF APPROVAL

The Department of Community Planning & Building of the City of Carmel-by-the-Sea has approved a Project pursuant to the City's Municipal Code. Persons interested in the project may review additional materials available at the Department of Community Planning & Building located at City Hall on Monte Verde Street between Ocean and 7th Avenues, phone number 831-620-2010.

The decision to approve this project may be appealed within 10 days from the date of this by filing a written appeal with the Department of Community Planning & Building.

Planning Case #: Design Study 23255
Owner Name: CHRISTENSEN DOUGLAS L TR ET AL
Case Planner: Evan Kort, Associate Planner
Date Posted:
Date Approved: 02/20/2024
Project Location: Torres 3 SE of 1st Avenue
APN #: 010101017000 BLOCK/LOT: 14/ALL LOT 6
Annlicant: Samuel Pitnick

Project Description: Approval of Design Study, DS 23-255 (Christensen), authorizes an amendment to a previously approved Design Study, DS 20-082, for the replacement of seven (7) existing wood framed windows and replacement of one (1) window with a new sliding glass door on the historic "Harry Turner Jr. House". The project maintains an active building permit (BP 20-336) and is located at on Torres 3 southeast of 1st Avenue in the Single Family (R-1) Zone District and shall be constructed consistent with the application materials dated prepared by Samuel Pitnick dated approved by the Community Planning and Building Department on February 20, 2024 as well as the Phase II Historic Evaluation prepared by Margret Clovis dated February 2, 2024, on file in the Community Planning & Building Department, unless modified by the conditions of approval.

Can this project be appealed to the Coastal Commission? Yes \square No \checkmark

Upon completion of the 10 calendar-day appeal period, please return this form, along with the Affidavit of Posting, to the case planner noted above.

DS 23-255 (Christensen) Conditions of Approval February 20, 2024 Page 1 of 2

	CONDITIONS OF APPROVAL
No.	Standard Conditions
1.	Authorization. Approval of Design Study, DS 23-255 (Christensen), authorizes an amendment to a previously approved Design Study, DS 20-082, for the replacement of seven (7) existing wood framed windows and replacement of one (1) window with a new sliding glass door on the historic "Harry Turner Jr. House". The project maintains an active building permit (BP 20-336) and is located at on Torres 3 southeast of 1st Avenue in the Single Family (R-1) Zone District and shall be constructed consistent with the application materials dated prepared by Samuel Pitnick dated approved by the Community Planning and Building Department on February 20, 2024 as well as the Phase II Historic Evaluation prepared by Margret Clovis dated February 2, 2024, on file in the Community Planning & Building Department, unless modified by the conditions of approval contained herein.
2.	Codes and Ordinances. The project shall be constructed in conformance with all requirements of the Single Family (R-1) Zone District, Beach and Riparian (BR) Overlay, and Park (P) Overlay. All adopted building and fire codes shall be adhered to in preparing the working drawings. If any codes or ordinances require design elements to be changed, or if any other changes are requested at the time such plans are submitted, such changes may require additional environmental review and subsequent approval by the Planning Commission.
3.	Permit Validity. This approval shall be valid for a period of one year from the date of action unless an active building permit has been issued and maintained for the proposed construction.
4.	Modifications. The applicant shall submit in writing, with revised plans, to the Community Planning and Building staff any proposed changes to the approved project plans prior to incorporating those changes. If the applicant changes the project without first obtaining City approval, the applicant will be required to submit the change in writing, with revised plans, within 2 weeks of the City being notified. A cease work order may be issued any time at the discretion of the Director of Community Planning and Building until: a) either the Planning Commission or Staff has approved the change, or b) the property owner has eliminated the change and submitted the proposed change in writing, with revised plans, for review. The project will be reviewed for its compliance to the approved plans prior to final inspection.
5.	Tree Removal. Trees on the site shall only be removed upon the approval of the City Forester or Forest and Beach Commission, as appropriate; all remaining trees shall be protected during construction by methods approved by the City Forester.
6.	Indemnification. The applicant agrees, at his or her sole expense, to defend, indemnify, and hold harmless the City, its public officials, officers, employees, and assigns, from any liability; and shall reimburse the City for any expense incurred, resulting from, or in connection with any project approvals. This includes any appeal, claim, suit, or other legal proceeding, to attack, set aside, void, or annul any project approval. The City shall promptly notify the applicant of any legal proceeding, and shall cooperate fully in the

Property Owner Signature

Applicant Signature

DS 23-255 (Christensen) Conditions of Approval February 20, 2024 Page 2 of 2

	defense. The City may, at its sole discretion, participate in any such legal action, but									
	participation shall not relieve the applicant of any obligation under this condition. Should									
	any party bring any legal action in connection with this project, the Superior Court of the									
	County of Monterey, California, shall be the situs and have jurisdiction for the resolution									
	of all such actions by the parties hereto.									
7.	Conditions of Approval. All conditions of approval for this planning permit (DS 23-255),									
	as well as all prior conditions of approval from prior planning approvals (DS 20-082; DS									
	21-057; DS 22-189), shall be printed on a full-size sheet and included with the									
	construction plan set submitted to the Building Safety Division.									
	SPECIAL CONDITIONS									
8.	Building Permit Revision & Prior Conditions of Approval. A revision to building permit BP 20-336 (H&R Investment Group LLC/Christensen) shall be applied for and obtained prior to commencement of work. All Conditions of Approval associated with prior Planning Approvals for the associated Building Permit (DS 20-082; DS 21-057; DS 22-189) are hereby incorporated into these Conditions of Approval by reference.									
9.	 Consistency with Secretary's Standards. Required: Prior to Building Permit issuance, the applicant shall revise the project plans to include the cut sheet(s) for the sliding glass door so that their suitability can be confirmed (refer to associated Phase II Evaluation; Standard #9). Recommended: It is recommended the width of the landing adjacent to the new sliding door be widened to the full width of the new door. If widened, a commensurate amount of (permeable or impermeable, as appropriate) site coverage shall be elsewhere on the site. The location of the removed site coverage shall be clearly identified on the site plan and the project data table revised accordingly (refer to associated Phase II Evaluation; Standard #9). 									
Ackno	wledgement and acceptance of conditions of approval:									

Once signed, please email to ekort@cbts.us

Printed Name

Printed Name

Date

Date

GENERAL NOTES

- CONTRACTOR TO FIELD VERIFY SURVEY AND EXISTING CONDITIONS PRIOR TO CONSTRUCTION AND SHALL NOTIFY THE ARCHITECT IN WRITING OF ANY DISCREPANCIES.
- 2. CONTRACTOR SHALL PROTECT EXISTING TREES AND ROOT SYSTEM. ALL EXCAVATION AROUND EXISTING TREES SHALL BE MADE BY HAND.
- 3. CULTURAL, ARCHAEOLOGICAL, HISTORICAL, OR PALEONTOLOGICAL RESOURCES NOTIFICATION: "STOP WORK WITHIN 50 METERS (165 FEET) OF UNCOVERED RESOURCE AND CONTACT THE CITY OF CARMEL AND A QUALIFIED ARCHAEOLOGIST IMMEDIATELY IF CULTURAL, ARCHAEOLOGICAL, HISTORICAL, OR PALEONTOLOGICAL RESOURCES ARE UNCOVERED".
- 4. SMOKE DETECTORS IN THE MAIN DWELLING SHALL BE INSTALLED AND FIELD VERIFIED IN EACH BEDROOM, IN THE HALLWAY LEADING TO THE BEDROOMS AND ON EACH FLOOR PER CRC R314.2. CARBON MONOXIDE ALARMS SHLL BE INSTALLED AND FIELD VERIFIED ON EACH FLOOR PER CRC R315.2.
- 5. THE ISSUANCE OF A PERMIT SHALL NOT PREVENT THE BUILDING OFFICIAL FROM REQUIRING THE CORRECTION OF ERRORS ON THESE PLANS OR FROM PREVENTING ANY VIOLATION OF THE CODES ADOPTED BY THE CITY, RELEVANT LAWS, ORDINANCES, **RULES AND/OR REGULATIONS**
- 6. CONTRACTOR TO OBTAIN AN 8-1-1/DIG ALERT TICKET PRIOR TO PERMIT ISSUANCE AND TO MAINTAIN THE TICKET IN ACTIVE STATUS AND ON SITE FOR INSPECTION THROUGHOUT THE PROJECT.
- 7. THE ELECTRICAL SERVICE LATERAL SHALL BE PLACED UNDERGROUND IN ACCORDANCE WITH CARMEL MUNICIPAL CODE 15.36.020. NOTE: PG&E REPORTS DELAYS OF UP TO 1 YEAR ON THE DESIGN AND INSTALLATION OF UNDERGROUND LATERALS IN CARMEL. CONTRACTOR SHALL APPLY EARLY. A CERTIFICATE OF OCCUPANCY WILL NOT BE ISSUED UNTIL PERMANENT POWER IS INSTALLED AND APPROVED

PROPOSED MATERIALS



NEW ALUMINUM FRAMED WINDOWS TO MATCH (E)



NEW ALUMINUM CLAD SLIDING GLASS DOOR TO MATCH (E)

EXISTING SITE PHOTOS




STREET VIEW OF HOUSE, LOOKING EAST



FRONT OF HOUSE, LOOKING SOUTHEAST



SOUTH SIDEYARD OF HOUSE, LOOKING EAST



NORTH SIDEYARD OF HOUSE, LOOKING EAST

SHEET INDEX


G1.0 PROJECT INFORMATION A1.0 EXISTING & PROPOSED SITE PLANS A2.0 EXISTING FLOOR PLAN A2.1 PROPOSED FLOOR PLAN A3.0 BUILDING ELEVATIONS A3.1 **BUILDING ELEVATIONS** A3.2 **BUILDING ELEVATIONS** A4.0 PRODUCT CUT SHEETS

SCOPE OF WORK


MINOR REMODEL OF AN EXISTING SINGLE FAMILY HOUSE. REPLACE (7) EXISTING WINDOWS, LIKE FOR LIKE. REPLACE (1) EXISTING WINDOW WITH NEW SLIDING GLASS DOOR. NEW WINDOWS TO BE AN ALL ALUMINUM PRODUCT FROM 'ALL WEATHER'. NEW SLIDING GLASS DOOR TO BE ALUMINUM CLAD PRODUCT FROM 'KOLBE'. INSTALL A 3'Wx1'D BRICK STEP AT THE NEW SLIDING GLASS DOOR. REMOVE 3 SF FROM EXISTING BRICK PATIO AT BACK OF HOUSE TO OFFSET ADDED LOT COVERAGE. INSTALL (1) NEW EXTERIOR DOWNLIGHT AT SLIDING GLASS DOOR.

THE EXISTING WINDOWS ARE ALL SINGLE PANE WHICH CREATES SIGNIFICANT HEAT LOSS IN THE HOME AS WELL AS CONDENSATION ISSUES LEADING TO WATER INTRUSION IN THE HOME. THE EXISTING WINDOWS ARE NON-TEMPERED AND DO NOT COMPLY WITH THE BEDROOM EGRESS REQUIREMENTS RESULTING IN UNSAFE CONDITIONS.

PARCEL MAP



VICINITY MAP



PROJECT TEAM

OWNER **DOUG & VALERI CHRISTENSEN** TORRES 3 S.E. OF 1ST AVENUE

CARMEL-BY-THE-SEA, CA 93921

ARCHITECT SAMUEL PITNICK ARCHITECTS, INC. LICENSE # C-34362

PO BOX 22412, CARMEL, CA 93922 PHONE: (831) 241-1895 SAMUELPITNICK@GMAIL.COM

STRUCTURAL ENGINEER JRT ENGINEERING, INC. P.O. BOX 51697

PACIFIC GROVE, CA 93950 PHONE: (831) 372-5890

SURVEYOR RASMUSSEN LAND SURVEYING, INC. 2150 GARDEN ROAD, SUITE A-3,

> MONTEREY, CA 93942 PHONE: (831) 375-7240

CONTRACTOR T.B.D.

PROJECT INFORMATION

PROPERTY ADDRESS TORRES 3 S.E. OF 1ST AVENUE CARMEL-BY-THE-SEA, CA 93921

BLOCK: 14 LOT: 6

U / CARPORT

010-101-017

ZONING R-1 (SINGLE FAMILY RESIDENTIAL)

TYPE OF CONSTRUCTION TYPE V-B

R-3 / SINGLE FAMILY RESIDENCE **OCCUPANCY GROUP**

YEAR BUILT 1948 (REMODELED 2021)

BUILDING INFORMATION & LOT COVERAGE

LOT SIZE 4,000 SF ALLOWABLE FLOOR AREA 1,800 SF

(E) FLOOR AREA 1,663 SF (NO CHANGES PROPOSED)

ALLOWABLE LOT COVERAGE 396 SF (556 SF WITH BONUS)

(E) LOT COVERAGE 546.25 SF (60.7% PERMEABLE)

(P) LOT COVERAGE 546.25 SF (60.7% PERMEABLE) PROVEI *SEE SITE PLANS FOR MORE INFORMATION ON LOT COVERAGE PROVEI

02/20/2024

MISCELLANEOUS Planning & Building

CAL AM WATER SOURCE

WASTE DISPOSAL SYSTEM SEWER - C.A.W.D.

NONE TREES TO BE REMOVED

NONE GRADING ESTIMATES

1 SPACE (COVERED) (E) PARKING

(E) BUILDING SPRINKLERED YES

BUILDING CODE INFO

THIS PROJECT SHALL COMPLY WITH THE FOLLOWING:

2022 CALIFORNIA RESIDENTIAL CODE 2022 CALIFORNIA BUILDING CODE

2022 CALIFORNIA MECHANICAL CODE 2022 CALIFORNIA PLUMBING CODE

2022 CALIFORNIA ELECTRICAL CODE

2022 CALIFORNIA ENERGY CODE 2022 CALIFORNIA FIRE CODE

2022 CALIFORNIA GREEN BUILDING STANDARDS CODE

ALL MATERIALS & CONSTRUCTION TO COMPLY WITH CHAPTER 7A OF

THE 2022 CBC, AND CHAPTER 3, SECTION 337R OF THE 2022 CRC.

TORRES RESIDENCE TORRES 3 S.E. OF 1ST **AVENUE**



0 ш N H H


City of Carmel-by-the-Sea REVISIONS DATE


> **ARCHITECTURAL** PROJECT INFORMATION

Scale: SEE DWG. Drawn By: SBP


Job: -

G1.0










- FIELD CONDITIONS PRIOR TO ORDERING WINDOWS & DOORS.
- 4. ALL DIMENSIONS ARE GIVEN FOR OVERALL FRAME SIZE
- 5. ALL HEAD HEIGHTS TO ALIGN WHERE POSSIBLE
- 6. ALL OPERABLE WINDOWS TO BE PROVIDED WITH SCREENS. 7. REQUIRED SAFETY GLAZING SHALL CONFIRM TO THE HUMAN IMPACT
- LOADS PER CRC SECTIONS R308.3 & R308.4.
- 8. GLAZING SHALL BE TEMPERED IN AN INDIVIDUAL FIXED OR OPERABLE PANEL THAT MEETS ALL OF THE FOLLOWING CONDITIONS: (A) THE EXPOSED AREA OF AN INDIVIDUAL PANE IS LARGER
 - THAN 9 SQUARE FEET; AND (B) THE BOTTOM EDGE OF THE GLAZING IS LESS THAN 18
- INCHES ABOVE THE FLOOR; AND
- (C) THE TOP EDGE OF THE GLAZING IS MORE THAN 36 INCHES ABOVE THE FLOOR; AND
- (D) ONE OR MORE WALKING SURFACES ARE WITHIN 36 INCHES, MEASURED HORIZONTALLY AND IN A STRAIGHT LINE OF THE GLAZING; AND
- (E) GLAZING IN ENCLOSURES FOR, OR WALLS FACING BATHTUBS & SHOWERS WHERE THE BOTTOM EDGE OF THE GLAZING IS LESS THAN 60 INCHES MEASURED VERTICALLY ABOVE ANY STANDING OR WALKING SURFACE.
- (F) FIXED AND OPERABLE PANELS OF SWINGING, SLIDING, AND BI-FOLD DOOR ASSEMBLIES.
- 9. GLAZING SHALL BE TEMPERED IN AN INDIVIDUAL FIXED OR OPERABLE PANEL ADJACENT TO A DOOR WHERE THE NEAREST VERTICAL EDGE IS WITHIN A 24-INCH ARC OF THE DOOR IN A CLOSED POSITION AND WHOSE BOTTOM EDGE IS LESS THAN 60 INCHES ABOVE THE FLOOR OR WALKING SURFACE.
- 10. CONTRACTOR TO PROVIDE SHOP DRAWING TO ARCHITECT FOR REVIEW PRIOR TO ORDERING DOORS AND WINDOWS. 11. ALL WINDOWS TO BE DUAL GLAZED - ARGON FILLED WITH THERMAL
- SPACER 12. MIN. U-VALUE & SGHC = SEE TITLE 24 REPORT
- 13. EXTERIOR WINDOWS AND EXTERIOR GLAZED DOORS SHALL BE MULTIPANE GLAZING WITH A MINIMUM OF ONE TEMPERED PANE, GLASS BLOCK UNITS, HAVE A FIRE RESISTANCE RATING OF 20 MINUTES WHEN TESTED IN ACCORDANCE WITH NFPA 257, OR MEET THE REQUIREMENTS OF SFM 12-7A-2. [§R327.8.2.1]
- 14. EXTERIOR DOORS SHALL BE OF APPROVED NONCOMBUSTIBLE CONSTRUCTION OR IGNITIONRESISTANT MATERIAL, SOLID CORE WOOD HAVING STILES AND RAILS NOT LESS THAN 1-3/8 INCHES THICK WITH INTERIOR FIELD PANEL THICKNESS NO LESS THAN 1- 1/4 INCHES THICK, SHALL HAVE A FIRE-RESISTANCE RATING OF NOT LESS THAN 20 MINUTES WHEN TESTED ACCORDING TO NFPA 252, OR MEET THE REQUIREMENTS OF SFM-7A-1. [§R327.8.3]



	DOOR SCHEDULE						
ΓAG	WIDTH	HEIGHT	THICK	DOOR MTL.	FRAME MTL.	TYPE	COMMENTS
06a	6'-0"	6'-8"	-	ALUM. CLAD/ GLASS	ALUM. CLAD	SLIDING	TEMPERED GLAZING,
							EGRESS

	WINDOW SCHEDULE						
TAG	WIDTH	HEIGHT	THICK	WINDOW MTL.	FRAME MTL.	TYPE	COMMENTS
1	4'-4"	4'-2"		GLASS	ALUM.	X-O-X	TEMPERED GLAZING, EGRESS
2	4'-4"	4'-2"		GLASS	ALUM.	X-O-X	TEMPERED GLAZING
3	4'-4"	4'-2"		GLASS	ALUM.	X-O-X	TEMPERED GLAZING
4	5'-8"	4'-2"		GLASS	ALUM.	X-O-X	TEMPERED GLAZING
5	4'-4"	4'-2"		GLASS	ALUM.	X-O-X	TEMPERED GLAZING
6	3'-0"	3'-0"		GLASS	ALUM.	CASEMENT	TEMPERED GLAZING
7	3'-0"	3'-0"		GLASS	ALUM.	CASEMENT	TEMPERED GLAZING,
							FROSTED



- (P) EXTERIOR LED DOWNLIGHT 'CYLINDER WALL SCONCE' BY KICHLER
- (P) SINGLE SWITCH, WITH DIMMER U.N.O.

PROPOSED FLOOR PLAN

SCALE: 1/4"=1'-0"

11250 LED Outdoor Wall Sconce

By Kichler

Product Options Finish: Textured Architectural Bronze, Textured Black

Details Designed in 2015

 Material: Metal • Dark Sky compliant, Title 24 compliant ETL Listed Wet Made In China

Dimensions

Lighting


Temp: 3000K Lifespan: 40000 hours **Additional Details**

Product URL: https://www.lumens.com/11250-led-outdoor-wall-scone-by-kichler-uu530320.html Rating: ETL Listed Wet



PROPOSED EXTERIOR DOWNLIGHT

TORRES RESIDENCE TORRES 3 S.E. OF 1ST **AVENUE** CARMEL, CA 93921



<u>U</u> MU N P E


REVISIONS DATE


Call Us 877.445448620/2024


ARCHITECTURAL PROPOSED

FLOOR PLAN

Scale: SEE DWG. Drawn By: SBP Job: -









SERIES 5000

2 1/4" WINDOW SYSTEM

The Series 5000 Window System is All Weather's most popular and cost effective thermally broken window design. Utilizing a pour & debridge thermal break, the Series 5000 offers energy efficiency without sacrificing performance or aesthetics.

Utilizing extruded, age hardened aluminum that boasts a T-6 rating for strength and durability, the Series 5000 window is built to last with a wall thickness that meets or exceeds commercial window standards. Economical, durable and beautiful, the Series 5000 is the ideal projected custom window solution for residential and multi-family applications.

FEATURES

- 2 ¼" Frame with mitered corners
- Fixed, casement, awning, hopper & combination configurations
- Max casement size of 36" x 60"
- Max fixed lite size 50 square feet Exterior Glazed
- Thermally broken frame Pour & Debridge system

FRAME OPTIONS

- Standard Nail On Panning Nail On
- Equal Leg / Comp Channel
- Equal Leg / F-Clip Z-Bar

GLAZING OPTIONS

- 1" OA insulated units
- 1" Simulated Divided Lite (SDL) Flat or beveled bar
- 2 ¾" True Divided Lite (TDL) Square or beveled bead

- HARDWARE OPTIONS Roto operator with butt hinges
- Cam handle with friction hinge Multi-point lock with roto operator

FINISH OPTIONS

- Clear Anodized, Class I (standard)
- Bronze Anodized, Class I (standard)
- Kynar Paint (color matching available) Custom Anodized (available)

RATINGS & CERTIFICATION

- NFRC Certified Product Commercial Rating C50
- Acoustically Rated

TORRES RESIDENCE TORRES 3 S.E. OF 1ST **AVENUE** CARMEL, CA 93921



PITNICK
MEL. CA 93922

SAMUEL
P.O. BOX 22412, CARN
PHONE: (831) 241-1899
EMAIL: SAMUELPITNIC

Assembly Drawings










SERIES 5000 CONFIGURATIONS ASSEMBLY DRAWINGS


NAIL ON FIXED / AWNING / FIXED SDL PICTURE AWNING





PROPOSED WINDOW CUT SHEETS











777 Aldridge Road I Vacaville, CA 95688 I P: 707.452.1600 I www.allweatheraa.com

27

APPROVED

02/20/2024

Scale: SEE DWG. Drawn By: SBP

ARCHITECTURAL

PRODUCT CUT SHEETS

REVISIONS DATE

A4.0

SAMUEL PITNICK ARCHITECTS

PO Box 22412, Carmel, CA 93922

(t) 831.241.1895 (e) samuelpitnick@gmail.com (w) samuelpitnick.com

City of Carmel-by-the-Sea Community Planning & Building Department Re: DS 23-255 (Christensen)

December 11, 2023

Dear Mr. Kort,

The following is an evaluation of the existing windows, at the Christensen Residence, in response to your completeness review letter dated 9/20/2023. The window and door numbers listed below correspond to those numbers shown on the drawings dated 8/11/2023 and originally submitted to the City as part of our application.

Window #1:

a.Window location - Bedroom #1, north elevation.

b.Photo of each window





c.Condition of paint/finish – Paint is starting to peel/chip off due to underlying rust issues. d.Condition of the frame and sill – Frame is warped preventing window from opening. Rust is visible and causing paint to peel.

e.Condition of the sash (frame, rails, and stiles) - Sash is warped preventing window from opening. Rust is visible and causing paint to peel.

f.Glazing problems – Single pane glass is not tempered creating safety issues.

Condensation accumulates inside of glazing which ultimately will lead to damaged sills and jambs. Home experiences major heat loss due to single pane glass.

g.Condition and inventory of hardware – Window crank is stripped and does not work. Exterior hinges show signs of rust making operation difficult.

h.The overall condition of the window - Poor. Contractor recommends replacement. The current window creates a major safety concern as egress from the bedroom is not possible.

Window #2:

a. Window location – Living room, north elevation.






- c.Condition of paint/finish Paint is starting to peel/chip off due to underlying rust issues.
- d. Condition of the frame and sill Rus Playsible and Building paints peel.
- e.Condition of the sash (frame, rails, and stiles) Rust is visible and causing paint to peel.
- f.Glazing problems Single pane glass is not tempered creating safety issues.


Condensation accumulates inside of glazing which ultimately will lead to damaged sills and jambs. Home experiences major heat loss due to single pane glass.

- g.Condition and inventory of hardware Windows are difficult to open due to rust issues.
- h.The overall condition of the window Poor. Contractor recommends replacement.

Window #3:

a. Window location – Living room, north elevation.





c.Condition of paint/finish - Paint is starting to peel/chip off due to underlying rust issues.

- d.Condition of the frame and sill Frame is warped preventing window from opening. Rust is visible and causing paint to peel.
- e.Condition of the sash (frame, rails, and stiles) Sash is warped preventing window from opening. Rust is visible and causing paint to peel.
- f.Glazing problems Single pane glass is not tempered creating safety issues.
- Condensation accumulates inside of glazing which ultimately will lead to damaged sills and jambs. Home experiences major heat loss due to single pane glass.
- g.Condition and inventory of hardware Hardware is not able to open window due to issues mentioned above.
- h.The overall condition of the window Poor. Contractor recommends replacement.

Window #4:

- a.Window location Living room, west elevation.
- b.Photo of each window



- c.Condition of paint/finish Paint is starting to the excelled the tent derlying rust issues.
- d.Condition of the frame and sill Rust is visible and causing paint to peel.
- e.Condition of the sash (frame, rails, and stiles) Rust is visible and causing paint to peel.
- f.Glazing problems Single pane glass is not tempered creating safety issues.
- Condensation accumulates inside of glazing which ultimately will lead to damaged sills and jambs. Home experiences major heat loss due to single pane glass.
- g.Condition and inventory of hardware Windows are difficult to open due to rust issues.
- h.The overall condition of the window Poor. Contractor recommends replacement.

Window #5:

- a.Window location Dining room, west elevation.
- b.Photo of each window




- c.Condition of paint/finish Paint is starting to peel/chip off due to underlying rust issues.
- d.Condition of the frame and sill Rust is visible and causing paint to peel.
- e.Condition of the sash (frame, rails, and stiles) Rust is visible and causing paint to peel.
- f.Glazing problems Single pane glass is not tempered creating safety issues.
- Condensation accumulates inside of glaz Ag Mici Rulina by will be ad to damaged sills and jambs. Home experiences major heat loss due to single pane glass.
- g.Condition and inventory of hardware Windows are difficult to open due to rust issues.

Window #6:

a.Window location – Kitchen, south elevation Carmel-by-the-Sea b.Photo of each window

Planning & Building Dept.



c.Condition of paint/finish - Paint is starting to peel/chip off due to underlying rust issues.

d.Condition of the frame and sill - Rust is visible and causing paint to peel.

e.Condition of the sash (frame, rails, and stiles) - Rust is visible and causing paint to peel.

f.Glazing problems - Single pane glass is not tempered creating safety issues. Condensation accumulates inside of glazing which ultimately will lead to damaged sills and jambs. Home experiences major heat loss due to single pane glass.

g.Condition and inventory of hardware – Window is seized and unable to open.

h.The overall condition of the window - Poor. Contractor recommends replacement.

Window #7:

a.Window location - Bathroom #1, south elevation.

b.Photo of each window





c.Condition of paint/finish - Paint is starting to peel/chip off due to underlying rust issues.

- d.Condition of the frame and sill Rust is visible and causing paint to peel.
- e.Condition of the sash (frame, rails, and stiles) Rust is visible and causing paint to peel.
- f.Glazing problems Condensation accumulates inside of glazing which ultimately will lead to damaged sills and jambs. Home experiences major heat loss due to single pane glass.
- g.Condition and inventory of hardware Window is seized and unable to open.
- h. The overall condition of the window Pear Pontrado recommends replacement.

Window #8 (Proposed door 106a):

a.Window location – Bedroom #2, south elevation / 20/2024 b.Photo of each window

City of Carmel-by-the-Sea Planning & Building Dept.



c.Condition of paint/finish - Paint is starting to peel/chip off due to underlying rust issues.

d.Condition of the frame and sill - Rust is visible and causing paint to peel.

e.Condition of the sash (frame, rails, and stiles) - Rust is visible and causing paint to peel.

f.Glazing problems - Single pane glass is not tempered creating safety issues.

Condensation accumulates inside of glazing which ultimately will lead to damaged sills and jambs. Home experiences major heat loss due to single pane glass.

g.Condition and inventory of hardware - Wanks Predized and In ble to open.

h.The overall condition of the window – Poor. Contractor recommends replacement. The current window creates a major safety concern as egress from the bedroom is not possible.

02/20/2024

The contractor has also prepared an additional evaluation of the existing window conditions and the proposed costs to repair each. See next sheet Each window unit would cost between \$8,500 and \$9,000 to repair and replace glass making it cost prohibitive. To install new thermally broken aluminum windows with the proper safety ideal gase glass would be significantly cheaper. Approximately \$1,500 to \$2,000 per unit.

Lastly, the existing windows were repaired, bonded, and repainted as recently as 2021 when the house underwent a remodel. The rust has already come back through the new paint and the hardware and window frames are starting to seize up again as a result. No amount of bonding and painting will ultimately prevent future rusting and repairs.

For these reasons we ask that the City support our application to replace the existing windows.

Sincerely,

Samuel Pitnick

Samuel Pitnick Architects, Inc.

Phone: (831) 241-1895

Email: samuelpitnick@gmail.com

APPROVED

02/20/2024

City of Carmel-by-the-Sea Planning & Building Dept.

SJ Ferrante Builders, Inc.

PO Box 52, Monterey, CA 93942 License # 848507 Phone 831-655-1636 Fax 831-655-1644 Cell 831-212-6962

> FOR: TORRES 3 SE OF 1ST APN#: 010101017000

DATE: DECEMBER 1, 2023

Window Report

TO: Mr. Doug Christensen Torres 3 SE of 1st cc. Samuel Pitnick

	DESCRIPTION	AM	OUNT
1.	Front Left Window of front door evidence of rust in all bottom corners. To repair this window you would have extensive amount of welding, all glass has to be removed and all work would have to be completed in shop. 40 hours of labor, \$2,200.00 in materials, painting and install	Vindow #4	8,500.0
2.	Front Right Window of front door evidence of rust in all bottom corners. To repair this window V you would have extensive amount of welding, all glass has to be removed and all work would have to be completed in shop. 40 hours of labor, \$2,200.00 in materials, painting and install		8,500.0
3.	Left side of house window #1 extensive damaged does not open and close, window is warped.	Vindow #1	9,000.0
4.	Front side of house window #2, evidence of rust in all bottom corners. To repair this window you would have extensive amount of welding, all glass has to be removed and all work would have to be completed in shop. 40 hours of labor, \$2,200.00 in materials, painting and install, window also needs all new panes	Vindow #2	9,000.0
5.	Left side window #3 is completed seized and cannot operate. \$ 9,000.00 for repairs	ndow #3	9,000.0
6.	Right side of house window # (kitchen). Rust all areas and window appears to be seized and is W in bad condition	indow #6	8,500.0
7.	bad condition.	lindow #7	8,500.0
8.	Window #4, Right side of house. It is damage and seized.	oor 106a	9,000.0
	APPROVED		
	NOTES – These windows have been repaired and bonded over the years. They have also been painted repeatedly. Heavy rust appears where it makes it impossible to weld to existing window. All windows need to be built new. This can be done in the property of		
Ş	The above report has been completed by Sal Ferrante, SJ Ferrante Builders, Inc. & American Metal Works, Blake Flores. City of Carmel-by-the-Sea		
	Planning & Building Dept.		
	-		
		2	

Phase Two Report for the Harry Turner House (APN 010-101-017) Carmel-by-the-Sea, CA.

Executive Summary

Built in 1948, the Harry Turner House is located on Torres Street 3 SE of First Avenue. In 2019 the property was evaluated for historical significance using the California Register for Historic Resources criteria and found eligible for listing under Criterion Three (Architecture) within the historic context theme of Architectural Development. Harry Turner used brick for his Minimal Traditional style house, a deviation from the usual wood, but a choice that reflects Carmel's pronounced taste for individualism. The three generations of Turners that contributed to the development of Carmel's building stock are not listed as significant craftsmen in the Historic Context Statement, however it is clear that their skill contributed to the unique masonry elements that have distinguished Carmel's residential and commercial architecture for decades. The Harry Turner House exhibits his fine craftsmanship and is an example of the Village's transition into post World War II residential trends. The Harry Turner House was listed on the Carmel Inventory of Historic Resources on March 3, 2020.

Very few changes were made to the house prior to 2022. In 2022 a 481 square foot, single-story addition was added to the rear elevation. The non-historic carport was removed and replaced with a 220 square foot garage. A Phase II report dated May 20, 2020, found the proposed work consistent with the Secretary of the Interior's Standards for Rehabilitation.

Character-Defining Features

A character-defining feature is an aspect of a building's design, construction, or detail that is representative of the building's function, type, or architectural style. Generally, character-defining features include specific building systems, architectural ornament, construction details, massing, materials, craftsmanship, site characteristics and landscaping within the period of significance. The period of significance for the Harry Turner House is 1948 (the date of construction).

In order for an important historic resource to preserve its significance, its character-defining features must be retained to the greatest extent possible. An understanding of a building's character-defining features is a crucial step in developing a plan that incorporates an appropriate level of rehabilitation. The Harry Turner House is a unique example of the Minimal Traditional style of architecture. The character-defining features include:

- Minimal decoration
- Brick siding
- Small scale plan
- Multi-paned fenestration
- Simple, flat roofline

Proposed Project Description

The project includes the replacement of seven aluminum windows in three locations as follows:

a) Two windows on the front elevation

- b) Three windows on the north elevation
- c) Two windows on the south elevation

The project also includes the removal of the bedroom window on the south elevation. The opening will be expanded to accommodate a sliding glass door to provide required egress. The windows in the Harry Turner House are considered character-defining features.



Figure 1: View of Harry Turner House, front elevation.

The Secretary of the Interior's Standards for Rehabilitation

Compliance Evaluation

As a historical resource, the Harry Turner House is subject to review under the California Environmental Quality Act (CEQA). Generally, under CEQA, a project that follows the *Standards for Rehabilitation* contained within *The Secretary of the Interior's Standards for the Treatment of Historic Properties* is considered to have mitigated impacts to a historical resource to a less-than-significant level (CEQA Guidelines 15064.5).

The compliance of the proposed work on the Harry Turner House is reviewed below with respect to the *Rehabilitation Standards*. The Standards are indicated in italics, followed by a discussion regarding the project's consistency or inconsistency with each Standard.

Rehabilitation is defined as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values." (36 CFR 67.2(b)).

Standard One

A property will be used as it was historically or be given a new use that requires minimal change to its distinctive materials, features, spaces, and spatial relationships.

The Harry Turner House has been a single-family residence since it was constructed in 1948. The proposed project does not change the historic use of the house. The proposed work is consistent with Standard One.

Standard Two

The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize the property will be avoided.

In order to retain and preserve the historic character of the property, the physical condition of the windows proposed for replacement was assessed (see Standard Six) and it was determined that replacement windows are necessary. In addition, a window will be removed and replaced with a sliding glass door on the south elevation. ITS Bulletin 22¹ advises:

"Generally, to meet the Standards, a new entrance should be simple in design; it should not appear historic; it should blend in with the historic façade; and it should be unobtrusive and modestly scaled. Adding a new entry on a secondary elevation of a building should not give that elevation excessive prominence, nor should it 'reorient' the building or detract from the historic entrance. In other words, the historic front of the building should still read clearly as the primary entrance."

The proposed sliding glass door will be located on a secondary elevation towards the rear of the house. It will not "reorient" the house and the front entrance will still take precedence. No features, spaces, or spatial relationships will be impacted by either project. The proposed work is consistent with Standard Two.

Standard Three

Each property will be recognized as a physical record of its time, place, and use. Changes that create a false sense of historical development, such as adding conjectural features or elements from other historical properties, will not be undertaken.

No conjectural features or architectural elements that would create a false sense of history are planned for the project. This Standard is not applicable.

Standard Four

Changes to a property that have acquired historic significance in their own right will be retained and preserved.

No changes to the property have acquired historical significance in their own right. This Standard is not applicable.

¹ ITS Bulletin 22. Interpreting the Secretary of the Interior's Standards for Rehabilitation. *Adding New Entrances to Historic Buildings*. October 2001.

Standard Five

Distinctive materials, features, finishes, and construction techniques or examples of craftsmanship that characterize a property will be preserved.

The installation of the sliding glass door will remove some of the brick siding, but the amount will be minimal. It is recommended that the removed siding be saved and stored in case future repairs to the siding are needed. The proposed work is consistent with Standard Five.



Figure 3: View of Harry Turner House from Torres Street.

Standard Six

Deteriorated historic features will be repaired rather than replaced. Where the severity of deterioration requires replacement of a distinctive feature, the new feature will match the old in design, color, texture, and where possible, materials. Replacement of missing features will be substantiated by documentary and physical evidence.

The following windows will be replaced as part of this project:

- a) Two windows on the front (west) elevation
- b) Three windows on the north elevation
- c) Two windows on the south elevation

A conditions survey was conducted by the project architect, Samuel Pitnick, dated December 11, 2023. This survey determined that the listed windows are beyond repair. Specifically, he stated that condensation has led to the warping and rusting of the window sash and frames. Condensation is also damaging the sills and jambs. The Secretary of the Interior's Standards and Guidelines for Rehabilitation

recommends, "Replacing windows that are too deteriorated to repair using the same sash and pane configuration." The conditions survey states that the windows will be replaced in kind, using the same materials, design, color, texture, and dimensions². A second window assessment report, dated December 1, 2023, was prepared by contractor Sal Ferrante and Blake Flores from American Metal Works. They reported that the windows were repaired, bonded, and repainted for the 2021 remodel. However, rust is already coming through the new paint and the windows are once again beginning to fail. Their report came to the same conclusions, and they recommended replacing the windows in kind. The proposed work for the windows is consistent with Standard Six.

Standard Seven

Chemical or physical treatments, if appropriate, will be undertaken using the gentlest means possible. Treatments that cause damage to historic materials will not be used.

Surface cleaning is not proposed for this project. This Standard is not applicable.

Standard Eight

Archeological resources will be protected and preserved in place.

No archeological resources have been located on the site. This Standard is not applicable.

Standard Nine

New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work shall be differentiated from the old and will be compatible with the historic materials, features, size, scale, and proportion, and massing to protect the integrity of the property and its environment.

The proposed sliding glass door will be an aluminum clad door from Kolbe. Per Plan Sheet A3.1, it appears that the new sliding glass door on the south elevation will be simple in design, unobtrusive, and it will not appear historic, per the recommendations found in ITS Bulletin 22. However, a cut sheet for the sliding glass door should be included in the plans in order to confirm its suitability for the project. In addition, rather than having a single brick step to the door it is recommended to enlarge the step so it will be the width of the window (see plan sheet A3.1). If the cut sheet confirms that the proposed sliding glass door is appropriate, then the proposed work will be consistent with Standard Nine.

Standard Ten

New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

This project does not include new additions or related new construction. This Standard is not applicable.

² The new windows will be aluminum and manufactured by "All Weather" windows.

Conclusion

The proposed project meets Standards One, Two, Five and Six of the Secretary of the Interior's Standards and Guidelines for Rehabilitation. Standards Three, Four, Seven, Eight, and Ten are not applicable. The proposed project will be consistent with Standard Nine if the cut sheet for the sliding glass door is included in the plans and their suitability can be confirmed.

Respectfully Submitted,

Margaret Clovis